PALGRAVE PARISH COUNCIL - RISK ASSESSMENT - ASSETS, as at March 2023

| Asset | Location(s) | What could go wrong? | How Likely? | Impact? | Consequences? | Mitigation/Action if risk occurs | Most recent photos for maintenance |
|--|---|---|----------------------|--------------|-------------------------------------|--|--|
| Bus Shelter & Notice Board | Priory Road Wanosial Maste | Lack of Maintenance, Physical Damage, Natural Aging, Flyposting | Possible Bossible | High High | Loss of use | Regular Inspection & Maintenance/ Repair or Replace, Remove Posters | |
| | Churchyard, Manorial Waste Village Green | uprooting due to Weather or Age, Lack of Maintenance, Physical Damage | Logginis | Moderate | Property Damage | Oct 22 – the internal felt needs replacing as it has deteriorated in so many places that is it probably easier to replace than repair. Needs a good clean cobweb clear. The overhanging tree was cut back in 2022 to limit damp ingress. | |
| BT Kiosk | Manorial Waste opp Church | Phone stops working, Wear and Tear | Possible | Moderate | Loss of use | Oct 22 – needs a good clean inside, remove cobwebs and wash with soapy water inside and out | |
| Dog Bins | Lows Lane, Lion Rd, Upper Rose Lane, Barnaway, PDCC, Millway Lane, Iower Crossing Rd nr railway | aging process. Damage due to traffic accidents to traffic accidents | Possible | Moderate | Loss of use | Regular Inspection/Repair or Replace Oct 22 – all in good order. No action required Batteries | |
| Fencing & Gates | Cemetery | Lack of Maintenance, Physical Damage, Natural Aging | Possible | Slight | Loss of use | Regular Inspection/Repair or Replace Oct 22- Repairs required to the main gate — awaiting spring '23 for these to be carried out. Quote received and approved. | |
| Footway Lighting | The Green, Priory Rd, Lows Lane, Crossing Rd, Upper Rose Lane | Physical Damage, Failure, Life-expired | Possible | Moderate | Loss of Use | Routine Maintenance by Suffolk CC. Replace if damaged, failed or Life-expired by Current Type of Lighting. Inspected annually by SCC and reported back to us. | |
| Gravestones & Memorials | Cemetery, Churchyard | Physical Damage, Soil Movement, Loosen over Time, Decay | Possible | Moderate | Personal Injury, Property Damage | Regular Inspection/Reset, Repair or SUGLAN Replace, Remove or Re-site | |
| Cemetery granite sign | Cemetery, Churchyard | Physical Damage, Soil Movement, Loosen over Time, Decay | Possible | Slight | Personal Injury, Property Damage | Regular Inspection/Reset, Repair or Replace, Remove or Re-site Oct 22 – Needs a clean with soapy water The Actions Balber Deuch on the Lewis Balber Deuch of the Lewis Balber | PALGRAVO, TOTAL PARTIES OF THE PARTI |
| Parish Council Notice Board 269guß | Cemetery, The Green, Manorial Waste, Lows Lue Green | Lack of Maintenance, Physical Damage, Flyposting, Rain ingress | Possible | High | Loss of Use | Regular Inspection & Maintenance/Repair or Replace, Remove Posters Oct 22- no action required. | |
| Asset | Location(s) | What could go wrong? | How Likely? | | Consequences? | Mitigation/Action if risk occurs | Most recent photos for maintenance |

Updated MARCH 2023 Page 1 of 3 **RISK ASSESSMENT - Assets**

Physical Damage

| Asset | Location(s) | What could go wrong? | How Likely? | Impact? | Consequences? | Mitigation/Action if risk occurs | Most recent photos for maintenance |
|-------------------------------|---|---|-------------|----------|-------------------------------------|--|------------------------------------|
| Seating | Cemetery, The Green, | Lack of Maintenance, | Possible | Slight | Loss of Use | Regular Maintenance/Repair, Replace or | |
| | Manorial Waste, Lows | | | | | Muite OttReplace, Remove Posters | |
| | <u>Faue3reen</u> | Aging f Maintenance, | Possible | High | Loss of Use , | 1.Oct 22- the Diamond Jubilee bench near | |
| Cemetery granite sign | Churchyard | Physical Damage, Soil Movement, Loosen over Time, Decay | Possible | Slight | Personal Injury, Property Damage | the pond has 2 supports that have come away from the main structure and need rewelding into place or similar 2. The Victoria Barber bench on the Manorial waste has been cleaned and restored by the family in 2022. No further action required. | |
| Cemetery | Cemetery | | Docrible | Citaba | Barranal Infinite | 3. The Guy Abthorpe bench on the Manorial | |
| Gravestones & Memorials | Cemetery, Churchyard | Physical Damage, Soil Movement, Loosen over Time, Decay | Possible | Moderate | Personal Injury, Property Damage | Waste needs a good wire brushing, cleaning and a coat of preservative 4. The Alfie & Charlie bench in the Cemetery | |
| Footway Lighting | The Green, Priory Rd, Lows Lane, Crossing Rd, Upper Rose Lane | Physical Damage, Failure, Life-expired | Possible | Moderate | Loss of Use | needs a good wire brushing, cleaning and a coat of preservative. 5. The G Lembo bench in the Cemetery needs no action. 6. The lows bench is Ok but needs clearing | |
| Gates | | Physical Damage, Natural Aging | | | | around it i.e nettles cut back and weedkiller applying. | |
| Speed Indicator Devices | 3 in total at Denmark Hill; Lion Rd and Upper Rose Lane | Batteries stop working due to aging process. Damage due to traffic accidents byksical Damage | Possible | High | Loss of Use | Regular inspection / Repair or Replace Batteries Sept 22 – The Lion Road SID completely refurbished f.o.c. | |
| Strimmer | Cllr Weston's Garage | Lack of Maintenance, Misuse, Breakdown, Life-expired | Possible | Moderate | Personal Injury, Loss of use | Regular Maintenance, check Users, Safety Equipment/Repair or Replace | |
| Trees | Cemetery, Churchyard, Manorial Waste Village Green | Branches falling or Tree uprooting due to Weather or Age, Lack of Maintenance, Physical Damage | Possible | Moderate | Personal Injury, Property Damage | 5-yearly Arboricultural Inspections, Regular Maintenance/Arrange for Tree Specialist to carry out works Mar 22 – obtaining a report of the trees on the Green and any initial maintenance to be carried out. | |
| Village Green | Priory Road | Lack of Maintenance, | Possible | High | Loss of Use | Missing or damaged bollards replace Dec 22 | |

RISK ASSESSMENT - Assets Updated March 2023

to enhance its protection from vehicle wear

and tear. Ongoing protection plan.

| Asset | Location(s) | What could go wrong? | How Likely? | Impact? | Consequences? | Mitigation/Action if risk occurs | Most recent photos for maintenance |
|--------------------|----------------|---|-------------|----------|-------------------------------------|--|------------------------------------|
| Village Sign | Manorial Waste | Lack of Maintenance, Physical Damage, Natural Aging | Possible | High | Loss of Use | Regular Maintenance/ Repair or Replace Oct 22 – sign removed for complete remake by original artist. Awaiting finished result. | PAI GRAVE |
| Walling & Gates | Churchyard | Lack of Maintenance, Physical Damage, Natural Aging | Possible | Slight | Personal Injury, Property Damage | Regular Inspection & Maintenance/ Secure Area if Safety Risk, Arrange for Specialist Repair Oct 22 – Ivy removed from the Church Wall and weedkiller applied. Churchyard Gates – Quote received & approves for repairs together with the cemetery gate repairs. Awaiting Spring '23. | |
| War Memorial | Churchyard | Lack of maintenance, Physical Damage, Decay | Possible | Moderate | Personal Injury, Property Damage | Regular Inspection/ Repair or Replace | |
| Village Pond | The Green | Silting up, weed overgrowth | Possible | High | Lose the asset if not maintained | Regular Inspection & Maintenance. Risk assessment suggested. Awaiting possible recommendations from inquest in Spring '23 due to death early December. | |